

Airworthiness Directive 49-04-01

January 3, 1949, covers this same subject.)

Federal Register Information

**Header Information
DEPARTMENT OF
TRANSPORTATION**

Federal Aviation Administration

14 CFR Part 39

AD 49-04-01

**Airworthiness Directives; Beech Model 35
Airplanes
PDF Copy (If Available):**

**Preamble Information
AGENCY: Federal Aviation
Administration, DOT**

Regulatory Information

**49-04-01 BEECH: Applies to Model 35
Serial Numbers D-1 to D-1300, Except D-
69, D- 315, D-356, D-754, D-827, D-1117,
D-1120, D-1201, D-1251, D-1274, D-1278,
D-1285, D-1289, D-1290, D-1291, D-1293,
D-1295, D-1296, D-1298 and D-1299.**

**To be accomplished at next 100-hour
inspection but not later than May 1, 1949.**

**Remove aileron control wheel drive chain
assembly from the control arm of the
specified aircraft, which have not had the
chain replaced by Beech facilities, and
visually inspect the pin through each link
for proper up-set heads on each end of the
pin. Chains having end ferrules dyed
green have been replaced by Beech
facilities and need not be inspected.**

(Beech Service Bulletin No. 35-8, revised