

8/23/01

9742Y

2001 Annual Inspection

12.00 lunch JC Flyg Service - Wally

- 1) sent out suction gauge to fix it from sticks ✓
- 2) prop cable adjustment ✓
- 3) oil consumption seems to have stabilized
- 4) ~~Nose~~ gear indicator in pedestal reset it
- 5) new seals on fuel caps
- 6) replaced ps left mag
- 7) new ps on both mags
- 8) replaced spring on impulse couplings on right mag.
(he replaced that ^{RT mag} last year too)

So need to keep an eye on that

I won't notice it in the magch.

compression in 60's normal for 10470
lowest 62

8/26

9742Y

ck altimeter accuracy → is it 200ft off?

ck VOR accuracy - one is dramatically different

Q - Service Bulletin re flap cables

Amy Johnson

7-8:00
11:00 regist.
12:30 - 1:00pm