

AIRWORTHINESS DIRECTIVE LISTING

**Frankfort Aviation Service, Inc.**

Storage • Rentals • FAA Approved Ground School • Instruction • Charter

RR 1, Box 168

CENTER ROAD - FRANKFORT, ILLINOIS 60423

815/469-2311

8-3-82

Tach 255.2

Bi-Weekly 82-14

A/C TT 2219.28

Eng. TT 337.16

AIRCRAFT MAKE	<u>Beechcraft</u>	ENGINE MAKE	<u>Continental</u>
MODEL	<u>35-B33</u>	MODEL	<u>IO-470K</u>
REG. #	<u>9742Y</u>	S/N	<u>92760R</u>
S/N	<u>CD-611</u>	S/N	<u>                    </u>

AD NUMBER	REVISION DATE	DATE / HOUR OF COMPLIANCE	METHOD OF COMPLIANCE	RECURRING (Yes-No)	NEXT COMPLIANCE DUE DATE / HOURS	AUTHORIZED SIGNATURE & NUMBER
49-26-01						
TRAILING	ANTENNA REWORK		NA by equipment			
49-48-01						
THOMPSON	FUEL PUMP		NA by equipment			
51-14-01						
FUEL BOOSTER PUMP REMOVAL			NA by equipment			
55-22-01						
OIL OUTLET CHECK VALVE			NA by S/N			
57-18-01	12/20/73					
FUSELAGE	BULKHEAD CRACKS		NA by Model			
62-08-03	7/9/70					
CONTROL WHEELS			NA by equipment			
69-18-01	8/30/69					
FUEL SYSTEM MODIFICATION			NA by S/N			
75-05-02	2/21/75					
ENGINE OIL			NA by equipment			
76-04-07	2/27/76					
EMERG. WINDOW			NA by equipment			
70-03-05	6/30/72	PCW 4/27/72 @ 1600 hrs	placards installed as required	No		<i>Duce Rebeck</i>
TURNING TYPE TAKEOFFS						
72-22-01	10/25/72	PCW Part (b) 7/12/74 @ 1787.0 hrs	installed new rollers and greased	Yes	Part (c) due each 100 hrs. Due again @ 255.5 tach	<i>Duce Rebeck</i> 7913904931
LANDING GEAR UPLOCK ROLLERS		C/W Part (c) 8-3-82 @ 255.5 tach				
72-11-02		PCW 7/12/74 @ 1787.0 hrs	placards installed as required	No		<i>Duce Rebeck</i>
ENG. FUEL	INTERRUPTION					

