

AD Compliance Report

Date: 6-9-1997

Registration #: **N9742Y**

Make: **BEECH**

Model: **35B33**

Serial #: **CD611**

Eng(s): **IO470 K (12B)**

Eng Serial #(s): **92760.R**

AD#	Subject	Date and Hours at Compliance	Recurring Yes/No	Next Due Date/Hours
72-22-01 Airframe	Landing gear uplock rollers	6/9/97	Yes	NEXT ANNUAL
	Effective Date: 10/25/72	Authorized Sig & Num: <u><i>J. Douglas AP 1819157</i></u>		
		Method of Compliance: GREASED UPLOCK		
	Supersedes: 72-17-02	Superseded by: N/A		
89-05-02 Airframe	Elevator control fittings	6-28-93 @ 2716	Yes	2816hrs
	Effective Date: 03/24/89	Authorized Sig & Num: _____		
		Method of Compliance: BY INSP P/CW		
	Supersedes: N/A	Superseded by: N/A		
93-24-03 Airframe	Rudder spar cracks	2791hrs	Yes	3291hrs
	Effective Date: 01/21/94	Authorized Sig & Num: _____		
		Method of Compliance: _____		
	Supersedes: 92-15-06	Superseded by: N/A		
95-04-03 Airframe	Spar failure	6/29/95 @ 2716	Yes	3216hrs
	Effective Date: 04/07/95	Authorized Sig & Num: _____		
		Method of Compliance: _____		
	Supersedes: 92-08-07	Superseded by: N/A		
96-12-07 Appliance	Impluse couplings	10/2/88@2409	Yes	2909hrs
	Effective Date: 07/18/96	Authorized Sig & Num: _____		
		Method of Compliance: _____		
	Supersedes: 78-09-07 R3	Superseded by: N/A		